

WORKOVER PROCEDURE

WELL NAME: WELLS RANCH USX BB01-23 **DATE:** 1/19/2016
LOCATION:
Qtr/Qtr: NE/SE Section: 1 Township: 5N Range: 63W
Footages: 1397 FSL: & 1053 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-25110

ENGINEER: BRIAN ULMER 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 471' KB Elevation: 4676'
Surface Cmt: 228 sx GL Elevation: 4664'
Long St Csg: 4-1/2" 11.6# M-80 @ 6727' TD: 6749'
Long St Cmt: 880 sx PBTD: 6711'
Long St Date: 6/8/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6330'-6344' & 6418'-6434'
Perforation Interval (2): Codell Perforations 6592'-6602'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 6578' Rods: N/A
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI for STEM.
COMMENTS: Uneconomic well. P&A for offset horizontal well drilling. Base of Fox Hills - 366'.

PROCEDURE:

- 1) MIRU workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6280'. Dump bail 2 sx of cement on top.
- 4) RIH w/ workstring and pump 50 sx balanced plug at 2500'. SI, WOC. If circulation maintained, no need to tag plug.
- 5) Unland casing. Cut casing off @ 600'. POOH with casing and lay down on trailer.
- 6) RIH w/ workstring to pump 190 sx stub plug where csg was pulled. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.