

WORKOVER PROCEDURE

WELL NAME: UPV 25-0114 **DATE:** 2/4/2016
LOCATION:
Qtr/Qtr: NENE Section: 25 Township: 4N Range: 64W
Footages: 663 FNL & 652 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-18057

ENGINEER: AJ Paine 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24# @ 533' KB Elevation: 4797'
Surface Cmt: 428 sx GL Elevation: 4787'
Long St Csg: 3 1/2", 7.7#, B-70 @ 7007' TD: 7023'
Long St Cmt: 186 sx PBTD: 6916'
Long St Date: 3/28/1994

Plug Back (Sand or CIBP): **Sand**
Perforation Interval (1): Codell Perforations: 6848' - 6861'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 1/16", 3.25#, J-55 @ 6827' Rods: _____
Pump: _____
Misc.: SN @ 6827'

PRODUCTION STATUS: 1.5 bopd and 20 mcf. 340/380 tubing/casing.
COMMENTS: Well can't payout WBI & STEM costs.

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tubing and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6798'.
- 4) RIH w/ workstring to pump 15 sx balance plug on top of CIBP to 6487' to cover Niobrara top.
- 5) Unland 3 1/2" casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 533'. Pump 225 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.