

WORKOVER PROCEDURE

WELL NAME: Larson A25-02 **DATE:** 2/10/2016
LOCATION:
Qtr/Qtr: NWNE Section: 25 Township: 6N Range: 64W
Footages: 676' FNL & 1786' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-14702

ENGINEER: NARAYAN CHOUDHARY 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 273' KB Elevation: 4650'
Surface Cmt: 275 sx GL Elevation: 4640'
Long St Csg: 2 7/8" 6.5# N-80 @ 6947' TD: 6950'
Long St Cmt: 285 sx PBTD: 6829'
Long St Date: 9/25/1990

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 6797' - 6810'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 2/3" 2.30# J-55 @ 6777' Rods: _____
Pump: _____
Misc.: Csg Patch @ 5197'

PRODUCTION STATUS: SI
COMMENTS: UNECONOMIC FOR WBI WORK

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 2/3" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6747'.
- 4) RIH w/ workstring pump 15sx of cement at 6747'.
- 5) RIH w/WL. Run CBL to confirm Casing Repair Cement
- 6) Unland casing. Cut casing off @ 2040'. POOH with casing laying down on trailer.
- 7) POOH to pump 100 sx stub plug @ 2040'. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 850'. Pump 255 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.