

## WORKOVER PROCEDURE

**WELL NAME:** Larson A25-01 **DATE:** 2/10/2016  
**LOCATION:**  
Qtr/Qtr: NENE Section: 25 Township: 6N Range: 64W  
Footages: 779' FNL & 659' FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-14701

**ENGINEER:** NARAYAN CHOUDHARY 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 273' KB Elevation: 4651  
Surface Cmt: 275 sx GL Elevation: 4641  
Long St Csg: 2 7/8" 6.5# @ 6948 TD: 6949  
Long St Cmt: 280 sx PBTD: 6834  
Long St Date: 9/29/1990

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6777' TO 6789'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 1/4" 2.33# J-55 @ 6744' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** SI  
**COMMENTS:** UNECONOMIC FOR WBI WORK

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6727'.
- 4) RIH w/ workstring pump 20sx of cement at 6727'.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 850'. Pump 255 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.