

WORKOVER PROCEDURE

WELL NAME: HSR WIEDEMAN 09-20 **DATE:** 2/11/2016

LOCATION:
Qtr/Qtr: NE/SE Section: 20 Township: 5N Range: 66W
Footages: 1800 FSL & 710 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-19149

ENGINEER: JOSH CHEBUL 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 23# @ 441' KB Elevation: 4882'
Surface Cmt: 310 sx GL Elevation: 4871'
Long St Csg: 4-1/2" 11.6# I-70 @ 7452' TD: 7473'
Long St Cmt: 220 sx PBTD: 7430'
Long St Date: 4/15/1996

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7043'-7045'
Perforation Interval (2): Codell Perforations 7309'-7319'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 7280' Rods: N/A
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing

COMMENTS: Well can't sustain cost required to upgrade battery.

PROCEDURE:

- 1) MIRU workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6993'. Dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing and lay down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 550'. Pump 175 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.