

WORKOVER PROCEDURE

WELL NAME: DESHAZO 24-41 **DATE:** 2/24/2016
LOCATION: Qtr/Qtr: NE/SE Section: 24 Township: 6N Range: 67W
Footages: 1939 FSL: & 568 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-23922

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 626' KB Elevation: 4761'
Surface Cmt: 280 sx GL Elevation: 4751'
Long St Csg: 4 1/2" 11.60#, M-80 @ 7261' TD: 7275'
Long St Cmt: 565 sx PBTD: 7246'
Long St Date: _____

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7096' - 7114'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" @ 7063' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7046', pump 23 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 676'. Pump 245 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.