

WORKOVER PROCEDURE

WELL NAME: GREENHEAD 11-18 **DATE:** 1/25/2016

LOCATION:
Qtr/Qtr: NE/SW Section: 18 Township: 4N Range: 66W
Footages: 2120 FSL & 1960 FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-12531

ENGINEER: JOSH CHEBUL 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 311' KB Elevation: 4721'
Surface Cmt: 250 sx GL Elevation: 4710'
Long St Csg: 4-1/2" 11.6# M-75 @ 7346' TD: 7346'
Long St Cmt: 220 sx PBTD: 7330'
Long St Date: 7/29/1985

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6896'-6914', 7002'-7010', & 7082'-7100'
Perforation Interval (2): Codell Perforations 7214'-7226'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 7197' Rods: N/A
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing

COMMENTS: Well is uneconomic to continue to produce.

PROCEDURE:

- 1) MIRU workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6846'. Dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing and lay down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 411'. Pump 130 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.