

WORKOVER PROCEDURE

WELL NAME: TYE USX A15-03D **DATE:** 3/4/2016
LOCATION:
Qtr/Qtr: SENW Section: 15 Township: 6N Range: 64W
Footages: 1376 FNL & 2483 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-33910

ENGINEER: JASON LEHMAN 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 907' KB Elevation: 4811'
Surface Cmt: 342 sx GL Elevation: 4797'
Long St Csg: 4-1/2" 11.6# M-80 @ 6944' TD: 7265'
Long St Cmt: 590 sx PBTD: 7211'
Long St Date: 9/1/2011

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 6933'-6945'; 7014'-7026'
Perforation Interval (2): Codell Perforations: 7102'-7114'
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 7077' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI for emissions compliance
COMMENTS: P&A for offset horizontal wells

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6883', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 50 sx balance plug @ 2500'. SI, WOC. If circulation maintained no need to tag plug.
- 5) Unland casing. Cut casing off @ 1660'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 1007'. Pump 324 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.