

**WORKOVER PROCEDURE**

**WELL NAME:** ROTHE STATE B36-08 **DATE:** 3/4/2016

**LOCATION:** Qtr/Qtr: SE/NE Section: 36 Township: 5N Range: 64W

Footages: 1976' FNL & 609' FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16705

**ENGINEER:** Jonathan Pomerantz 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 313' KB Elevation: 4597'  
Surface Cmt: 410 sx GL Elevation: 4587'  
Long St Csg: 2 7/8" 6.5# @ 6810' TD: 6817'  
Long St Cmt: 275 sx PBTD: 6786'  
Long St Date: 3/3/1993

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6624' - 6637'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1.66" 2.3# J-55 tbg @ 6602' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: Casing Patch @ 5199' (11/10/2010)

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
  - 2) POOH w/ 1.66" tbg and lay down.
  - 3) RU WL. RIH w/ CIBP. Set CIBP @ 6574'. RIH w/ workstring to pump 10 sx on top of CIBP.
  - 4) POOH w/ workstring to 2500'. Pump 7 sx courtesy plug. POOH w/ workstring.
  - 5) Unland casing (if able). Cut casing (in slips if unable to unland) @ 420'. POOH w/ casing laying down on trailer.
  - 6) RIH w/ workstring to 420'. Pump 140 sx shoe plug. Cement to surface.
  - 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
  - 8) Cut surface casing off 6'-8' below ground.
  - 9) Clean up location. Reclaim location. RDMO.