

WORKOVER PROCEDURE

WELL NAME: BLEHM 07 **DATE:** 2/29/2016

LOCATION: Qtr/Qtr: SW/SE Section: 24 Township: 5N Range: 67W

Footages: 645 FSL & 1995 Township: 5N Range: 67W
645 FSL & 1995 Township: 5N Range: 67W

COUNTY: WELD **STATE:** CO **API #:** 05-123-11217

ENGINEER: JOSH CHEBUL 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 268' KB Elevation: 5036'
Surface Cmt: 225 sx GL Elevation: 5026'
Long St Csg: 4-1/2" 11.60# J-55 @ 7619' TD: 7620'
Long St Cmt: 200 sx PBTD: 7572'
Long St Date: 7/5/1983

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7520'-7530'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2-3/8" 4.70# J-55 @ 7485' Rods: N/A
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing

COMMENTS: Well is uneconomic to continue to produce.

PROCEDURE:

- 1) MIRU workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7470'. POOH RD WL.
- 4) RIH w/ workstring to pump 30 sx plug atop CIBP at 7470' to cover Niobrara Formation. POOH w/ workstring.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing and lay down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 702'. Pump 220 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. RDMOL.