



Photo 1. View of rills in southern slope eroding toward an irrigation canal southeast of the project area.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Poor revegetation observed on this slope needs to be monitored and re-seeded in 2016 if vegetative cover is not increasing.



Photo 3. View of the western portion of the project area from the southwestern corner facing northward.



Photo 4. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation appears to be heavily grazed and should be monitored and re-seeded if vegetation is not increasing in fall 2016.



Photo 5 View of the northern portion of the project area from the northeastern corner facing westward. Grasses such as Indian ricegrass (*Achnatherum hymenoides*) and western wheatgrass (*Pascopyron smithii*) are growing here.



Photo 6. View of rig anchor cable in the southern portion of the project area. This needs to be removed.



Photo 7. View of area in the northeastern corner of the project area where stormwater flows off of the well pad and is eroding the slope northeast of the project area, shown in Photo 8.



Photo 8. View of stormwater erosion downstream from Photo 7, where stormwater flows are eroding a channel northeast of the project area. Channel is approximately 2 feet wide and 1 foot deep.