

WORKOVER PROCEDURE

WELL NAME: OTTOSON I12-12 DATE: 3/14/2016

LOCATION: Qtr/Qtr: NW/SW Section: 12 Township: 6N Range: 66W

Footages: 1980 FSL & 660 FWL

COUNTY: WELD STATE: CO API #: 05-123-29234

ENGINEER: JOHN HATCH 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17#, h-40 # @ 526' KB Elevation: 4803' Surface Cmt: 244 sx GL Elevation: 4793' Long St Csg: 4 1/2" 11.60#, M-80 @ 7386' TD: 7393' Long St Cmt: 510 sx PBSD: 7350' Long St Date: 2/11/2009

Plug Back (Sand or CIBP): Perforation Interval (1): Codell Perforations 7213' - 7230' Perforation Interval (2): Perforation Interval (3): Tubing: 2 3/8" 4.70#, J-55 @ 7190' Rods: Pump: Misc.:

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) POOH w/ 2 3/8" tbg and lay down. 3) RU WL. RIH w/ CIBP. Set CIBP @ 7163", pump 45 sx of cement on top. 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer. 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 6) POOH w/ workstring to 570'. Pump 249 sx shoe plug. Cement to surface. 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. RDMOL.