

WORKOVER PROCEDURE

WELL NAME:	OTTOSON I12-25		DATE:	3/14/2016	
LOCATION:					
Qtr/Qtr:	NW/SW	Section:	12	Township:	6N
Footages:	&		Range: 66W		
COUNTY:	WELD	STATE:	CO	API #:	05-123-29233
ENGINEER:	JOHN HATCH		7 Day Notice Sent:		
	(Please notify Engineer of any major changes prior to work)		Do not start operations until:		
			Notice Expires:		
OBJECTIVE:	P&A				
WELL DATA:					
Surface Csg:	7" 1#, H-40 @ 496'			KB Elevation:	4793'
Surface Cmt:	155 sx			GL Elevation:	4783'
Long St Csg:	4 1/2" 11.60#, M-80 @ 7379'			TD:	7382'
Long St Cmt:	520 sx			PBTD:	7304'
Long St Date:	2/17/2009				
Plug Back (Sand or CIBP):					
Perforation Interval (1):	Codell Perforations 7214' - 7228'				
Perforation Interval (2):					
Perforation Interval (3):					
Tubing:	2 3/8" 4.70#, J-55 @ 7185.5'			Rods:	
Pump:					
Misc.:					
PRODUCTION STATUS:					
COMMENTS:					

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7164', pump 35 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 546'. Pump 125 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.