

Michael Lee - Engineer
(970) 339-1499 - Office
(970) 302-4601 - Cell
Michael.Lee@anadarko.com

PLUG AND ABANDON PROCEDURE

Selby Pooling Unit 1

- 1 Gyro run 1/7/2015, well needs CBL.
- 2 Provide 48 hr notice to COGCC prior to rig up per request on approved Form 6. Submit Form 42 and call Automation Removal Group at least 24 hr prior to rig move. If not already completed, request that they catch and remove plunger, isolate production equipment and remove any automation equipment prior to the rig showing up. Install perimeter fence as needed.
- 3 MIRU SL. Fish bumper spring, and tag PBMD (should be +/- 7511'). Enter tag depth in OpenWells and contact Engineering to discuss potential changes. RDMO SL.
- 4 Prepare location for base beam rig.
- 5 Check and record Bradenhead pressure. If Bradenhead valve is not accessible, re-plumb so that valve is above GL. Blow down Bradenhead and re-check pressure the next day. Repeat until pressure stays at 0 psi. Contact Evans Engineering if pressure does not blow down to 0 and stay at 0.
- 6 Spot a minimum of 25 jts of 2-3/8" 4.7# J-55 EUE tbg.
- 7 MIRU WO rig. Circulate and kill well with fresh water and biocide. If unable to circulate, load tbg and csg with fresh water and biocide. ND WH, NU BOP.
- 8 PU tbg to break any possible sand bridges. Do not exceed 80% of tubing tensile strength, or 57,360 lb. LD landing jt. TOO H with 2-3/8" tbg. PU bit and scraper and RIH to +/- 7380'. TOO H, SB 6080' of 2-3/8" tbg. LD bit and scraper and remainder of tbg.
- 9 Notify cementers of the needed volumes: 130 sx of 1:1:3 Poz:G:Gel cement with 20% silica, 0.4% CFL-3, 0.4% CFR-2, and 0.1% SMS mixed at 13.5 ppg and 1.66 cf/sk (Niobrara suicide sqz); 135 sx of 0:1:0 Class G cement with 0.5% CFR-2, 0.2% FMC, 0.5% LWA, and 0.25 pps polyflake mixed at 15.8 ppg and 1.15 cf/sk (Shannon suicide squeeze); 850 sx of Type III cement with 0.3% CFL-3, 0.3% CFR-2, 0.25 pps polyflake and CaCl₂ mixed at 14.8 ppg and 1.33 cf/sk (Fox Hills stub plug).
- 10 MIRU WL. RIH with CIBP (4-1/2" 11.6#, K-55) and set at +/- 7370'. Load hole with biocide treated fresh water. Have WL standby.
- 11 TIH with 2-3/8" tbg down to 2500' and circulate all gas out of the hole with biocide treated fresh water. Pressure test CIBP to 1000 psi for 15 minutes. TOO H and SB all 2-3/8" tbg.
- 12 Well does not have CBL. PU and RIH w/ CCL-GR-CBL-VDL. Run log from 7370' to surface and send results to engineering to discuss. Dump 2 sx cement on bridge plug.
- 13 **Steps/depths could change based on outcome of CBL** PU and RIH with two perf guns and CCL inside 4-1/2" csg (3-1/8", 3 spf, "Big Hole" 0.6" EHD, 7" penetration, 120 deg phasing, 3' net, 6 total holes). Shoot 1' of bottom squeeze holes at 6450'. PUH to 6050' and shoot 2' of top squeeze holes. POOH, RDMO WL.
- 14 TIH with 4-1/2" CICR (4-1/2" 10.5#) on 2-3/8" tbg while hydrotesting to 4000 psi and set at +/- 6080'. Establish circulation with fresh water and biocide. If unable to circulate, contact Evans Engineering.
- 15 MIRU cement company. Pump 130 sx of 1:1:3 Poz:G:Gel cement with 20% silica, 0.4% CFL-3, 0.4% CFR-2, and 0.1% SMS mixed at 13.5 ppg and 1.66 cf/sk (cement from 6450' to 6050' inside and outside 4-1/2" csg, 9" avg hole from caliper, adding 20% excess). Under displace by 3 bbls (13 sx), sting out of CICR and dump remaining cement on CICR.
- 16 PUH to 5700'. Reverse circulate fresh water with biocide to clear tbg and remove gas from hole.
- 17 TOO H. Stand back 3720' of 2-3/8" tbg and LD remainder.
- 18 MIRU WL. PU and RIH with two perf guns and CCL inside 4-1/2" csg (3-1/8", 3 spf, "Big Hole" 0.6" EHD, 7" penetration, 120 deg phasing, 3' net, 6 total holes). Shoot 1' of bottom squeeze holes at 3890'. PUH to 3690' and shoot 2' of top squeeze holes. POOH, RDMO WL.
- 19 TIH with 4-1/2" CICR (4-1/2" 10.5#) on 2-3/8" tbg and set at +/- 3720'. Establish circulation with fresh water and biocide. If unable to circulate, contact Evans Engineering.

- 20 MIRU cement company. Pump 5 bbls fresh water, 20 bbls sodium metasilicate, and 5 bbls fresh water followed with 135 sx of 0:1:0 Class G cement with 0.5% CFR-2, 0.2% FMC, 0.5% LWA, and 0.25 pps polyflake mixed at 15.8 ppg and 1.15 cf/sk (cement from 50' below base of Shannon to 200' above top of Shannon, 10.5" hole from caliper, adding 20% excess). Under displace by 3 bbls (13 sx), sting out of CICR and dump remaining cement on CICR.
- 21 PUH to 3400' and reverse circulate fresh water with biocide to clear tbg.
- 22 TOO H. Stand back 1590' of tbg and LD remainder.
- 23 MIRU WL. PU jet cutter and RIH to 1490', cut 4-1/2" csg. Circulate to remove any gas and old mud from wellbore. RDMO WL.
- 24 ND BOP, ND tbg head. NU BOP on surface csg with 4-1/2" pipe rams. Install 3000 psi ball valves on csg head outlets. Install choke or choke manifold on one outlet.
- 25 TOO H with 4-1/2" csg and LD.
- 26 Uninstall 4-1/2" pipe rams on BOP and install 2-3/8" pipe rams.
- 27 TIH with 2-3/8" tbg to +/- 1590', 100' inside 4-1/2" csg stub.
- 28 MIRU cement company. Establish circulation with fresh water and biocide and get bottoms up. Pump 10 bbls SAPP, 20 bbls fresh water and biocide followed with 445 sx of Type III cement with 0.3% CFL-3, 0.3% CFR-2, 0.25 pps polyflake and CaCl₂ mixed at 14.8 ppg and 1.33 cf/sk (cement from 1590' to 800', 10.5" avg hole from SX caliper, adding 40% excess).
- 29 TOO H with 2-3/8" tbg and circulate with fresh water and biocide at ~500'. WOC per cementing company recommendation, tag plug w/ 2-3/8" tbg. Tag needs to be 800' or higher.
- 30 Establish circulation with fresh water and biocide and get bottoms up. Pump 10 bbls SAPP, 20 bbls fresh water and biocide followed with 405 sx of Type III cement with 0.3% CFL-3, 0.3% CFR-2, 0.25 pps polyflake and CaCl₂ mixed at 14.8 ppg and 1.33 cf/sk (cement from 800' to 120', 10.5" avg hole from SX caliper, adding 40% excess).
- 31 TOO H with 2-3/8" tbg and circulate with fresh water and biocide at ~95'. WOC per cementing company recommendation, tag plug. Tag needs to be 130' or higher. TOO H, LD.
- 32 MIRU WL. RIH with 8-5/8" CIBP and set at 80'. RDMO WL and RDMO WO rig.
- 33 Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries and invoices to rscDJVendors@anadarko.com within 24 hrs of the completion of the job.
- 34 Supervisor submit paper copies of all invoices, logs, and reports to Evans Engineering Specialist.
- 35 Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
- 36 Capping crew will set and secure night cap on 8-5/8" casing head, restrain the casing head, pressure test CIBP to 500 psi with hydrotest pump, then remove night cap and casing head restraints.
- 37 Excavate hole around surface casing enough to allow welder to cut 8-5/8" casing minimum 5' below ground level.
- 38 Welder cut 8-5/8" casing minimum 5' below ground level.
- 39 MIRU Redi Cement mixer. Use 4500 psi compressive strength cement, (NO gravel) to fill stubout.
- 40 Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
- 41 Properly abandon flowlines per Rule 1103.
- 42 Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
- 43 Back fill hole with fill. Clean location, level.
- 44 Submit Form 6 to COGCC ensuring to provide 'As performed' WBD identifying operations completed.