

WORKOVER PROCEDURE

WELL NAME: CECIL FARMS#06-14 **DATE:** 3/22/2016
LOCATION:
Qtr/Qtr: SE/NE Section: 6 Township: 6N Range: 66W
Footages: 1965' FNL & 682' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-22328

ENGINEER: John Hatch (Noble) # 303.505.6589 7 Day Notice Sent:
Nathan Foote (Halliburton) # 281-871-7889 Do not start operations until:
(Please notify Engineer of any major changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# (Grade not specified) @ 418' KB Elevation: 4888'
Surface Cmt: 200 sx GL Elevation: 4878'
Long St Csg: 4 1/2" 11.6# (Grade not specified) @ 7503' TD: 7508'
Long St Cmt: 815 sx PBSD: 7480'
Long St Date: 10/11/2004

Plug Back (Sand or CIBP):
Perforation Interval (1): Niobrara Perforations 7032' - 7261'
Perforation Interval (2): Codell Perforations 7340' - 7356'
Perforation Interval (3):
Tubing: 2-3/8" (Wt/Grade NS) @ 7332' Rods: NA
Pump: NA
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6982', dump bail 2 sx of cement on top.
- 4) RIH w/ CT to pump 20 sx courtesy plug from 2500' to 2300'.
- 5) Set a 80 sx shoe plug from 1000' to surface with CT. Bring cement to surface.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.