

WORKOVER PROCEDURE

WELL NAME: CARLSON 14-01 **DATE:** 3/31/2016
LOCATION:
Qtr/Qtr: NE/NE Section: 14 Township: 6N Range: 66W
Footages: 990 FNL & 851 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-10799

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 34# @ 435' KB Elevation: 4832'
Surface Cmt: 280 sx GL Elevation: 4821'
Long St Csg: 5 1/2" K-55 @ 7902' TD: 7902'
Long St Cmt: 250 sx PBDT: unknown
Long St Date: 9/9/1982

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7235' - 7249'
Perforation Interval (2): J Sand Perforations 7724' - 7752'
Perforation Interval (3): _____
Tubing: 2 1/16" @ 7656' Rods: _____
Pump: _____
Misc.: **FISH downhole, 2 1/16" tubing string & 2 Model D packers @ 7210' & 7680'**

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) TIH with WS to wash to TOF approx. @7184'
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 7184', dump bail 2 sx of cement on top.
- 6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 485'. Pump 213 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. RDMOL.