

Date 2/1/14	Company Bayswater E & P			Well Name & Number Winter 8-29		County Weld	State CO	API Number 05-123-37608	GL 4973	KB 4986
Report Day 5	TVD 7,373'	TMD 7,805'	PBTD 7,768'	QtrQtr Sec-Twp-Rge NENE Sec 29-T7N-R67W		Daily Cost \$11,167		Cumulative Cost \$77,868	AFE Amount	
Directions to Location Hwy 85 N to Hwy 392, W to Hwy 257, N to CR78, 1/10 mi W, S into									Supervisor Sears	
Actual Operations Current 24 Hours Clear shallow ice plug, tag sd @ 7480 ft, set CIBP @ 7478 ft & perf Niobrara B f/ 7450-7452 & 7460-7467 ft, 4 spf.										
Proposed Operations Next 24 Hours WO frac										
Time Log										
From	To	Hrs								
7:00	8:30	1:30	RU Allied to well.							
8:30	10:00	1:30	Open well. SIWP = 1500 psi. Feels slushy going down. Call for hot oiler. Call for methanol, not available.							
			POOH w/ WL to check what is in junk basket. Condensate/hydrates mixed with sand (did not see sand on 1/23/14).							
10:00	12:45	2:45	Load water on hot oiler. Pump ~100 deg water down well. Pressure up to ~4500 psi & bleed off several times, well acted like it was taking a little bit of fluid. Fill hot oiler line with ~25 gals MeOH and pump down and pressure up and bleed off.							
12:45	14:00	1:15	Hook up to flow back. Start at ~1300 psi on 14 choke, pressure going down and moving fluid. Rec 33 BF, pressure dropped to 50 spi. Pump ~15 BW down well with hot oiler. SI well							
14:00	15:15	1:15	RU WL lubricator to well. RIH w/ gauge ring, junk basket and weight bars. Correlate to short joint. Continue in the hole, stack out 7492 ft. Pull uphole to short joint. Felt like we pulling something up with WL, shook free at ~7330 ft. Go back down slowly, stack out at 7480 ft. Call for orders. POOH w/ WL. Sand in the junk basket.							
			Plan is to hook up with frac pumps to flush well bore. Will pump ~25 BW to flush sand back into Codell.							
15:15	16:30	1:15	Frac crew on loc. Hook up to well.							
16:30	17:00	0:30	PT to 6800 psi, set popoff to 5850 psi. Open well, 1180 psi. Establish rate with one pump. Pump 1.1 BW, pressure out to 5600 psi. Call for orders. Rig down frac crew.							
			Plan - forego Niobrara C, set CIBP @ 7475 ft. Perf Niobrara B as planned. Cut water delivery to loc and sand.							
			Magna to fill 24 tanks. Sand haulers already had ~400,000 lbs on loc.							
17:00	19:30	2:30	Call for Niobrara B gun from Allied's shop.							
19:30	21:15	1:45	Guns on location. Prepare guns. RIH w/ CIBP & guns. Correlate to short joint. Set CIBP @ 7478 ft.							
			Perforate Niobrara B f/ 7450-7452 & 7460-7467 ft, 4 spf, 19 gms charges, 0.41" EHD, 120 deg phasing. POOH gun.							
21:15	22:00	0:45	All shots fired. RD WL. Tarp well.							