

## WORKOVER PROCEDURE

**WELL NAME:** Loloff #01 **DATE:** 4/1/2016  
**LOCATION:**  
 Qtr/Qtr: NESW Section: 26 Township: 5N Range: 64W  
 Footages: 1980' FSL & 1980' FWL  
**COUNTY:** WELD STATE: CO API #: 05-123-11068

**ENGINEER:** Johnathan Pomerantz (Noble - 303-228-4198) 7 Day Notice Sent: \_\_\_\_\_  
Tanner Boyd (Halliburton - 432-803-6064) Do not start operations until: \_\_\_\_\_  
 (Please notify Engineer of any major changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8.625" 24# (Grade ?) SET AT 327' KB Elevation: 4622'  
 Surface Cmt: 280 sx GL Elevation: 4609'  
 Long St Csg: 4.5" 11.6# (Grade ?) SET AT 6811' TD: 6811'  
 Long St Cmt: 225 sx PBDT: 6766'  
 Long St Date: 3/30/1983

Plug Back (Sand or CIBP): \_\_\_\_\_  
 Perforation Interval (1): NIOBRARA Perforations 6444' - 6558'  
 Perforation Interval (2): CODELL Perforations 6728' - 6738'  
 Perforation Interval (3): \_\_\_\_\_  
 Tubing: 2.375" 4.7# @ 6430' Rods: NA  
 Pump: NA  
 Misc.: **SPUD DATE:** 3/25/1983 **TD DATE:** 3/30/1983

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** Composite flow through plug at 6620' - 6728'  
 \_\_\_\_\_  
No Sussex Production within a mile

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP at 6394', dump bail 2 sx of cement on top.
- 4) Perforate at 2500' and 427'.
- 5) Set CICR at 2400'.
- 6) RIH w/ CT and sting into CICR. Pump 87 sx cement below retainer, leaving 100' (8 sx) on top of CICR.
- 7) POOH and RD CT. Pump 175 sx (142 sx out & 33 sx in) shoe plug down production casing. Bring cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.