

WORKOVER PROCEDURE

WELL NAME: WADSWORTH 36-13 DATE: 4/5/2016

LOCATION: Qtr/Qtr: SW/NE Section: 36 Township: 7N Range: 67W

Footages: 1986' FNL & 1978' FEL

COUNTY: WELD STATE: CO API #: 05-123-25222

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 895' KB Elevation: 4932'
Surface Cmt: 350 sx GL Elevation: 4916'
Long St Csg: 4 1/2" 11.6# @ 7513' TD: 7544'
Long St Cmt: 690 sx PBTD: 7489'
Long St Date: 9/22/2007

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 7373' - 7386'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 3/8" 4.7# ? tbg @ 7330' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RIH w/ workstring and tubing-set CIBP. Set CIBP @ 7323'. Pump 30 sx cement on top of CIBP.
4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
6) POOH w/ workstring to 1000'. Pump 325 sx shoe plug. Cement to surface.
7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.