

WORKOVER PROCEDURE

WELL NAME: WADSWORTH 36-12 **DATE:** 4/5/2016

LOCATION: Qtr/Qtr: NW/NE Section: 36 Township: 7N Range: 67W

Footages: 662' FNL & 1980' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-25129

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 492' KB Elevation: 4954'
Surface Cmt: 350 sx GL Elevation: 4942'
Long St Csg: 4 1/2" 11.6# @ 7565' TD: 7580'
Long St Cmt: 670 sx PBTD: 7542'
Long St Date: 5/17/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7388' - 7406'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" ?# ? tbg @ 7356' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RIH w/ workstring and tubing-set CIBP. Set CIBP @ 7338'. Pump 30 sx on top of CIBP.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 675'. Pump 225 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.