

WORKOVER PROCEDURE

WELL NAME:	Monfort BB30-06		DATE:	3/24/2016	
LOCATION:					
Qtr/Qtr:	SE/NW	Section:	30	Township:	5N
Footages:	1975'	FNL	&	2000'	FWL
COUNTY:	WELD		STATE:	CO	
			API #:	05-123-15533	
ENGINEER:					
	Jonathan Pomerantz (Noble) # 303-228-4198		7 Day Notice Sent:		
	Nathan Foote (Halliburton) # 281-871-7889		Do not start operations until:		
	(Please notify Engineer of any major changes prior to work)		Notice Expires:		
OBJECTIVE:	P&A				
WELL DATA:					
Surface Csg:	8 5/8" 24# (Grade not Specified) @337.0'			KB Elevation:	4583.0'
Surface Cmt:	325 sx			GL Elevation:	4574.0'
Long St Csg:	2 7/8" 8.7# N-80 @ 6747.0'			TD:	6775.0'
Long St Cmt:	260 sx			PBTD:	6740'.0
Long St Date:	10/9/1992				
Plug Back (Sand or CIBP):					
Perforation Interval (1):	Codell Perforations 6596.0'-6607.0'				
Perforation Interval (2):					
Perforation Interval (3):					
Tubing:	1 1/4" 2.3# J-55 @ 6558.0'		Rods:	NA	
Pump:	NA				
Misc.:					
PRODUCTION STATUS:					
COMMENTS:	No producing Sussex within 1 mile.				

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1-1/4" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6546'.
- 4) Perforate at 2500' and 437'.
- 5) RIH w/ CT and pump 10 sx cement on top of CIBP @ 6546'. RIH w/ CIGR. Set CIGR @ 2400'.
- 6) RIH w/ CT and sting into CIGR. Pump 90 sx through and 5 sx on top.
- 7) POOH and RD CT. Pump 180 sx shoe plug down production casing. Bring cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.