

WORKOVER PROCEDURE

WELL NAME: Trebor #B10-15 **DATE:** 3/28/2016
LOCATION:
Qtr/Qtr: SWSE Section: 10 Township: 5N Range: 64W
Footages: 480' FSL & 1980' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-13382

ENGINEER: Johnathan Pomerantz (Noble - 303-228-4198) 7 Day Notice Sent: _____
Tanner Boyd (Halliburton - 432-803-6064) Do not start operations until: _____
(Please notify Engineer of any major changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8.625" 24# (Grade ?) SET AT 314' KB Elevation: 4603'
Surface Cmt: 175 sx GL Elevation: 4592'
Long St Csg: 4.5" 15.1# N-80 SET AT 6900' TD: 6924'
Long St Cmt: 220 sx PBTD: 6839'
Long St Date: 3/13/1987

Plug Back (Sand or CIBP): _____
Perforation Interval (1): NIOBRARA Perforations 6470' - 6640'
Perforation Interval (2): CODELL Perforations 6725' - 6738'
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# @ 6702 Rods: NA
Pump: NA
Misc.: SPUD DATE: 3/7/1987 TD DATE: 3/12/1987

PRODUCTION STATUS: _____
COMMENTS: Discrepancy in TD. DRL RPT TD 6905'; ST RPT 6904'; LOG TD 6924'

No Sussex Production within a mile

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP at 6420', dump bail 2 sx of cement on top.
- 4) Perforate at 2500' and 414'.
- 5) Set CICR at 2400'.
- 6) RIH w/ CT and sting into CICR. Pump 83 sx cement below retainer, leaving 100' (7 sx) on top of CICR.
- 7) POOH and RD CT. Pump 170 sx (140 sx out & 30 sx in) down production casing. Bring cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.