

WORKOVER PROCEDURE

WELL NAME: Cockroft USX A11-02 DATE: 4/8/2016
LOCATION: Qtr/Qtr: NW/NE Section: 11 Township: 6N Range: 64W
Footages: 480 FNL & 1860 FEL
COUNTY: WELD STATE: CO API #: 05-123-24709

ENGINEER: Jason Lehman (Noble) # 970-304-5221 7 Day Notice Sent:
Nathan Foote (Halliburton) # 281-871-7889 Do not start operations until:
(Please notify Engineer of any major changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24 # J-55 @ 861' KB Elevation: 4749'
Surface Cmt: 477 sx GL Elevation: 4739'
Long St Csg: 4-1/2" 11.6# M-80 @ 7073' TD: 7098'
Long St Cmt: 1040 sx PBTD: 7021'
Long St Date: 2/12/2007

Plug Back (Sand or CIBP):
Perforation Interval (1): Niobrara Perforations 6627' - 6768'
Perforation Interval (2): Codell Perforations 6924' - 6937'
Perforation Interval (3):
Tubing: 2 3/8" 4.70# J-55 @ 6900.4' Rods: NA
Pump: NA
Misc.:

PRODUCTION STATUS:
COMMENTS: No producing Sussex within 1 mile. The CBL used to perf NIO was incorrect- Discrepancy in file on which are correct.

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 2-3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6577', dump bail 2 sx of cement on top.
4) Perforate at 2500' and 961'.
5) Set CICR at 2400'.
6) RIH w/ CT and sting into CICR. Pump 95 sx cement, 87' below retainer, and leaving 100' (8 sx) on top of CICR.
7) POOH and RD CT. Pump 330 sx (257 sx out & 73 sx in) shoe plug down production csg. Bring cement to surface.
8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.