

WORKOVER PROCEDURE

WELL NAME: DANIELS K05-25 **DATE:** 3/9/2016
LOCATION:
Qtr/Qtr: SW/SW Section: 5 Township: 4N Range: 66W
Footages: 1262 FSL & 1095 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-22203

ENGINEER: JOSH CHEBUL 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 415' KB Elevation: 4715'
Surface Cmt: 160 sx GL Elevation: 4699'
Long St Csg: 4-1/2" 11.60# M-80 @ 7302' TD: 7332'
Long St Cmt: 360 sx PBTD: 7289'
Long St Date: 5/21/2004

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7162'-7179'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2-3/8" 4.70# J-55 @ 7155' Rods: N/A
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing
COMMENTS: Well is uneconomic to continue to produce.

PROCEDURE:

- 1) MIRU workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7112'. POOH RD WL.
- 4) RIH w/ workstring to pump 30 sx plug atop CIBP at 7112' to cover Niobrara Formation. POOH w/ workstring.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing and lay down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 515'. Pump 165 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. RDMOL.