

WORKOVER PROCEDURE

WELL NAME: Cally Blue D 15-11 **DATE:** 4/14/2016
LOCATION:
Qtr/Qtr: NESW Section: 15 Township: 3N Range: 64W
Footages: 2162 FSL & 2060 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-16287

ENGINEER: AJ Paine 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24# @ 515' KB Elevation: 4797'
Surface Cmt: 360 sx GL Elevation: 4807'
Long St Csg: 3 1/2", 7.7#, M-75 @ 7096' TD: 7118'
Long St Cmt: 360 + 230 sx PBTD: 7032'
Long St Date: 5/6/1993

Plug Back (Sand or CIBP): **Sand**
Perforation Interval (1): Sussex Perforations: 4335' - 4376'
Perforation Interval (2): Codell Perforations: 6958' - 6969'
Perforation Interval (3):
Tubing: 2 1/16", 3.25#, J-55 @ 6939' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: 0.25 bopd and 2 mcf. 250/250 tubing/casing.
COMMENTS: Well can't payout cost to comingle for STEM work.

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tubing and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6908'.
- 4) RIH w/ workstring to pump 15 sx balance plug on top of CIBP to 6590' to cover Niobrara top.
- 5) RU WL. RIH w/ CIBP. Set CIBP @ 4285'. Dump bail 2 sx cement on top.
- 6) Unland 3 1/2" casing. Cut casing off @ 2500'. POOH and laydown 3 1/2" casing.
- 7) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 708'. Pump 260 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.