

WORKOVER PROCEDURE

WELL NAME: Ruby Red D08-07 **DATE:** 4/18/2016
LOCATION:
Qtr/Qtr: SW/NE Section: 8 Township: 3N Range: 64W
Footages: 1980' FNL & 1980' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-16886

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @535' KB Elevation: 4743'
Surface Cmt: 400 sx GL Elevation: 4733'
Long St Csg: 4 1/2" 10.5# J-55 @ 7066' TD: 7115'
Long St Cmt: 870 sx PBTD: 7048'
Long St Date: 4/7/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perforations 4279' - 4319' (squeezed off 7/22/2003)
Perforation Interval (2): Codell Perforations 6950' - 6964'
Perforation Interval (3): _____
Tubing: 2-3/8" @ 6918' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: SI; surface equipment removed
COMMENTS: Flood plain

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6900', pump 30 sx cement on top to cover Nio top.
- 4) RIH w/ workstring to pump 30 sx balance plug @ 4469' to cover squeezed off sussex perms. If maintain circulation, no ne
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 635'. Pump 210 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.