

WORKOVER PROCEDURE

WELL NAME: FOSS 06-42 **DATE:** 4/15/2016
LOCATION:
Qtr/Qtr: NWSE Section: 6 Township: 6N Range: 63W
Footages: 2175 FSL: & 1777 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-24288

ENGINEER: JASON LEHMAN 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 454' KB Elevation: 4708'
Surface Cmt: 250 sx GL Elevation: 4696'
Long St Csg: 4-1/2" 11.6# M-80 @ 6982' TD: 6984'
Long St Cmt: 1274 sx PBTD: 6950'
Long St Date: 10/22/2008

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 6558'-6575'; 6632'-6644'; 6660'-6692'; 6726'-6742'
Perforation Interval (2): Codell Perforations: 6842'-6852'
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 6820' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI for emissions compliance
COMMENTS: TOC ~Surface

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RIH w/ workstring and tubing-set CIBP.
- 4) Set tubing-set CIBP @ 6508'. Pump 5 sx on top of CIBP.
- 5) POOH w/ workstring to pump 15 sx courtesy plug @ 2500'.
- 6) POOH w/ workstring to 554'. Pump 183 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.