

WORKOVER PROCEDURE

WELL NAME: Lilli Unit 10-06 DATE: 4/18/2016

LOCATION: Qtr/Qtr: NWSE Section: 6 Township: 8N Range: 58W

Footages: 1980' FSL & 1980' FEL

COUNTY: WELD STATE: CO API #: 05-123-13861

ENGINEER: Ben Zapp PE 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 184' KB Elevation: 4,812.00 Surface Cmt: 110 sx GL Elevation: 4,802.00 Long St Csg: 5 1/2" 17.5# @ 6617' TD: 6,620.00 Long St Cmt: 140 sx PBDT: 6,604.00 Long St Date: 3/24/1988

Plug Back (Sand or CIBP): Tag Perforation Interval (1): D Sand 6,477' - 6,485' Perforation Interval (2): Perforation Interval (3): Tubing: 2 3/8" @ 6,385' Rods: Yes Pump: Yes Misc.:

PRODUCTION STATUS: TA @ 6,385'

COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) POOH w/ rods, pump & 2-3/8" tbg and lay down. 3) RU WL. RIH w/ CIBP. Set CIBP @ 6,427', dump bail 2 sx of cement on top. 4) RIH and pump 10sxs over Nio top at 5,766' 5) Unland casing. Cut casing off @ 2,500'. POOH with casing laying down on trailer. 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 7) POOH w/ workstring to 850'. Pump 315 sx shoe plug. Cement to surface. (Water well at 695') 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 9) Cut surface casing off 6'-8' below ground. 10) Clean up location. Reclaim location. RDMO.