

## WORKOVER PROCEDURE

**WELL NAME:** KEHN USX AD19-11 **DATE:** 4/19/2016  
**LOCATION:**  
Qtr/Qtr: NESW Section: 19 Township: 7N Range: 62W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-26045

**ENGINEER:** Daniel Hodge 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 477' KB Elevation: 4763  
Surface Cmt: 232 sx GL Elevation: 4753  
Long St Csg: 4 1/2" 11.6# @ 6883' TD: 6904  
Long St Cmt: 720 sx PBTD: 6825  
Long St Date: 5/17/2008

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6507' - 6626'  
Perforation Interval (2): Codell Perforations 6730' - 6740'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 tbg @ 6812' Rods: 7/8" Rods - 89 jts, 3/4" Rods-180 jt  
Pump: 2" Insert Pump  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** CBL not in well file, on COGCC Website

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ rods and lay down.
- 3) Release tubing anchor. POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 6407', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off +/- 1600'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump (50) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 700'. Pump approx 240 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.