

WORKOVER PROCEDURE

WELL NAME: HERGENREDER BB32-10DI **DATE:** 4/22/2016
LOCATION:
Qtr/Qtr: NW/SE Section: 32 Township: 5N Range: 63W
Footages: 2185 FSL & 1797 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-21982

ENGINEER: Jon Lefor 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8 24# @ 672' KB Elevation: 4577
Surface Cmt: 400 SX GL Elevation: 4567
Long St Csg: 4 1/2 11.6# M-80 @ 7451 TD: 7451
Long St Cmt: 300 SX PBTD: 6627
Long St Date: 2/9/2004

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6250' - 6348'
Perforation Interval (2): Codell Perforations 6510' - 6522'
Perforation Interval (3): J-Sand Perforations 6974' - 7040'
Perforation Interval (4): Dakota Perforations 7272' - 7290'
Tubing: 2 3/8" 4.7# J-55 @ 6495' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6200', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 775'. Pump 300 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.