

WORKOVER PROCEDURE

WELL NAME: McClellan PC LG04-15 **DATE:** 4/25/2016
LOCATION:
Qtr/Qtr: SWSE Section: 4 Township: 8N Range: 59W
Footages: 830 FSL & 1810 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-33457

ENGINEER: Daniel Hodge 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 570' KB Elevation: 4856
Surface Cmt: 250 sx GL Elevation: 4843
Long St Csg: 4 1/2" 11.6# M-80 @ 6392' TD: 6415
Long St Cmt: 545 sx PBTD: 6347
Long St Date: 6/2/2011

Plug Back (Sand or CIBP): Cement C
Perforation Interval (1): Niobrara 6058 - 6162
Perforation Interval (2): Codell 6232 - 6239
Perforation Interval (3): _____
Tubing: 2 3/8 J-55 @ 6017 Rods: 230 3/4" rods
Pump: RHBC 1 1/4"
Misc.: _____

PRODUCTION STATUS: Not Producing
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Unseat Pump. POOH w/ rods and pump and lay down
- 3) POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 5850, dump bail 5 sx of cement on top.
- 5) Pump 50 sx courtesy plug @ 2500'
- 6) Unland casing. Cut casing off @ 900'. POOH w/ casing laying down on trailer.
- 7) Pump ~265 sx shoe plug at 900' where casing was cut. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.