

WORKOVER PROCEDURE

WELL NAME: STINAR C14-28D **DATE:** 4/26/2016
LOCATION:
Qtr/Qtr: NW/NE Section: 14 Township: 4N Range: 64W
Footages: 150 FSL & 2490 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-32786

ENGINEER: Jon Lefor 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8 24# J-55 @ 647' KB Elevation: 4650'
Surface Cmt: 196 SX GL Elevation: 4639'
Long St Csg: 4 1/2 11.6# M-80 @ 7012' TD: 6882'
Long St Cmt: 610 SX PBTD: 6778'
Long St Date: 11/17/2011

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6667' - 6749'
Perforation Interval (2): Codell Perforations 6852' - 6864'
Perforation Interval (3): _____
Perforation Interval (4): _____
Tubing: 2 3/8" 4.7# J-55 @ 6830' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6617', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 870'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to 870' to pump 350 sx stub plug/shoe plug combo where csg was pulled. Cement to surface.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.