

WORKOVER PROCEDURE

WELL NAME: Monfort E19-12 DATE: 4/27/2016
LOCATION: Qtr/Qtr: NW/SW Section: 19 Township: 6N Range: 65W
Footages: 1981' FSL & 665' FWL
COUNTY: WELD STATE: CO API #: 05-123-18683

ENGINEER: John Hatch 303.505.6589 7 Day Notice Sent:
B. Lawrence (Halliburton) 303.513.1199
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: Well Abandonment

WELL DATA: Surface Csg: 8-5/8"; 24 ppf; J-55; set at 427' KB Elevation: 4733'
Surface Cmt: 300 sx GL Elevation: 4723'
Long St Csg: 2-7/8"; 6.5 ppf; N-80; set at 7278' TD: 7280'
Long St Cmt: 205 sx PBDT: 7258.7'
Long St Date: 12/16/1994

Plug Back (Sand or CIBP):
Perforation Interval (1): Niobrara Perforations 6886' - 6968'
Perforation Interval (2): Codell Perforations 7104' - 7120'
Tubing: 1.66"; 2.33 ppf; J-55 @ 7097' Rods: NA
Pump: NA
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 1.66" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6836', dump bail 2 sx of cement on top.
4) Perforate at 2500' and 527'.
5) Set CICR at 2400'.
6) RIH w/ CT and sting into CICR. Pump 92 sx cement below retainer, leaving 100' (3 sx) on top of CICR.
7) POOH and RD CT. Pump 210 sx shoe plug down production casing. Bring cement to surface.
8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.