

## WORKOVER PROCEDURE

**WELL NAME:** SHAKLEE 01 **DATE:** 4/27/2016  
**LOCATION:**  
Qtr/Qtr: SW/SW Section: 2 Township: 4N Range: 64W  
Footages: 660 FSL & 660 FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-12101

**ENGINEER:** Jon Lefor 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8 24# J-55 @ 436' KB Elevation: 4630'  
Surface Cmt: 300 SX GL Elevation: 4620'  
Long St Csg: 4 1/2 10.5# J-55 @ 6857' TD: 6870'  
Long St Cmt: 250 SX PBTD: 6849'  
Long St Date: 1/9/1985

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): \_\_\_\_\_  
Perforation Interval (2): Codell Perforations 6755' - 6769'  
Perforation Interval (3): \_\_\_\_\_  
Perforation Interval (4): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 @ 6735' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RIH w/ workstring and tubing-set CIBP. Set CIBP @ 6705'. Pump 30 sx on top of CIBP.
- 4) POOH w/ workstring to 2500'. Pump 20 sx courtesy plug.
- 5) Unland casing. Cut casing off @ 730'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring to 730'. Pump 300 sx shoe/stub plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.