

WORKOVER PROCEDURE

WELL NAME: STROHAUER 18-24 DATE: 5/11/2016
LOCATION: Qtr/Qtr: SENW Section: 18 Township: 6N Range: 63W
Footages: 2179 FNL & 2025 FWL
COUNTY: WELD STATE: CO API #: 05-123-23806

ENGINEER: JASON LEHMAN 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 488' KB Elevation: 4668'
Surface Cmt: 220 sx GL Elevation: 4658'
Long St Csg: 4-1/2" 11.6# M-80 @ 6995' TD: 7008'
Long St Cmt: 696 sx PBTD: 6913'
Long St Date: 4/25/2007

Plug Back (Sand or CIBP): RBP @ 6730'
Perforation Interval (1): Codell Perforations: 6786'-6799'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 6122' Rods: _____
Pump: _____
Misc.: Nio Top ~6469'

PRODUCTION STATUS: SI for emissions compliance & WBI
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RIH w/ workstring to 6730'. Wash sand on top of RBP.
- 4) Pump 30 sx balance plug. SI, WOC. No need to tag if circulation is maintained.
- 5) POOH to 2500'. Pump 25 sx balance plug. SI, WOC. No need to tag if circulation is maintained.
- 6) Unland casing. Cut casing off @ ~1600'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 588'. Pump 194 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.