

WORKOVER PROCEDURE

WELL NAME: STROHAUER 18-21 **DATE:** 5/11/2016

LOCATION:
Qtr/Qtr: NENW Section: 18 Township: 6N Range: 63W
Footages: 848 FNL & 1645 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-23807

ENGINEER: JASON LEHMAN 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 454' KB Elevation: 4675'
Surface Cmt: 220 sx GL Elevation: 4663'
Long St Csg: 4-1/2" 11.6# M-80 @ 6930' TD: 7004'
Long St Cmt: 655 sx PBTD: 6872'
Long St Date: 4/19/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations: 6799'-6811'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 6794' Rods: _____
Pump: _____
Misc.: **Nio Top -6481'**

PRODUCTION STATUS: SI for emissions compliance

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6749', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 6711'. Pump 25 sx balance plug. SI, WOC. RIH. No need to tag if circulation is maintained.
- 5) Unland casing. Cut casing off @ ~2360'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 554'. Pump 217 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.