

FORM  
6Rev  
12/05

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

401047026

Date Received:

05/13/2016

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Jenifer Hakkarinen

Name of Operator: PDC ENERGY INC

Phone: (303) 8605800

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: Jenifer.Hakkarinen@pdce.com

For "Intent" 24 hour notice required,

Name: Peterson, Tom

Tel: (303) 815-9641

COGCC contact:

Email: tom.peterson@state.co.us

API Number 05-123-21965-00

Well Name: STATE CORSAIR

Well Number: 23-36

Location: QtrQtr: NESW Section: 36 Township: 4N Range: 68W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.268810

Longitude: -104.953670

GPS Data:

Date of Measurement: 09/26/2006

PDOP Reading: 2.2

GPS Instrument Operator's Name: Holly L. Tracy

Reason for Abandonment:

☐ Dry☒ Production Sub-economic☐ Mechanical Problems☐ Other

Casing to be pulled:

☒ Yes☐ No

Estimated Depth: 600

Fish in Hole:

☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☒ No

If yes, explain details below

Details:

## Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| CODELL    | 7336      | 7344      |                |                     |            |

Total: 1 zone(s)

## Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF        | 12+1/4       | 8+5/8          | 24              | 400           | 225          | 400        | 0          | VISU   |
| 1ST         | 7+7/8        | 4+1/2          | 10.5            | 7,535         | 190          | 7,535      | 6,380      | CBL    |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7300 with 2 sacks cmt on top. CIBP #2: Depth 7000 with 2 sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 230 sacks half in. half out surface casing from 700 ft. to 0 ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

State Corsair #23-36 (05-123-21965)/Plugging Procedure (Intent)

Producing formation: Codell

Existing Perforations: Codell - 7,336'-7,344'

TD: 7,560' PBD: 7,521'

Surface Casing: 8 5/8" 24# @ 400' w/ 225 sks cmt.

Production Casing: 4 1/2" 10.5# @ 7,535' w/ 190 sks cmt (TOC at 6,380').

Proposed Procedure:

1. MIRU pulling unit.
2. Blow down to tanks. Load with fluid to kill well.
3. Circulate and condition well for P&A ops.
4. TOOH with 235 jts of 2 3/8" production tubing.
5. Rig up wireline. RIH with CIBP. Set CIBP at 7,300'.
6. Load dump bailer with 2sx of 15.8#/gal CI G cement. RIH with dump bailer and spot on top of CIBP.
7. RIH with CIBP. Set CIBP at 7,000'.
8. Load dump bailer with 2sx of 15.8#/gal CI G cement. RIH with dump bailer and spot on top of CIBP.
9. RIH w/ casing cutter and cut production casing above TOC at 600'. Pull 4 1/2" casing out of hole.
10. TIH with workstring to 700'. Circulate and condition to prepare for surface plug.
11. RU cementers. Mix and pump cement stub plug to surface (700') with 230 sks of 15.8#/gal CL G cement. Confirm cement to surface.
12. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jenifer Hakkarinen

Title: Reg Tech Date: 5/13/2016 Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved, STEVE

COGCC Approved:

Date: 5/26/2016

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 11/25/2016

**COA Type**

**Description**

|  |   |
|--|---|
|  | Note changes to plugging procedure:<br>1) Provide 48 hour notice of plugging MIRU via electronic Form 42.<br>2) For the 700' plug: pump plug and displace. If surface casing plug is not circulated to surface then tag plug – must be at 350' or shallower and provide 10 sx plug at the surface. Leave at least 100' of cement in the casing for each plug.<br>3) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete.<br>4) Prior to initiation of plugging operations, a Bradenhead test shall be performed. If any pressure remains at the conclusion of the test or any liquids were present call COGCC Engineer for sampling requirements. Form 17 shall be submitted within 10 days. |
|--|---|

**Attachment Check List**

**Att Doc Num**

**Name**

|           |                         |
|-----------|-------------------------|
| 401047026 | FORM 6 INTENT SUBMITTED |
| 401047036 | WELLBORE DIAGRAM        |
| 401047037 | WELLBORE DIAGRAM        |

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

|             |  |                         |
|-------------|--|-------------------------|
| Engineer    | MOved CIBP from 7300' to 7286' to be between 50-100' above the top perforation, operator agreed. | 5/26/2016<br>8:56:05 AM |
| Public Room | Document verification complete 05/20/16  | 5/20/2016<br>9:47:48 AM |

Total: 2 comment(s)