

WORKOVER PROCEDURE

WELL NAME: Cervi 42-27 **DATE:** 6/2/2016
LOCATION:
Qtr/Qtr: SENE Section: 27 Township: 4N Range: 63W
Footages: 2042 FNL & 661 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-21031

ENGINEER: AJ Paine 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24# @ 534' KB Elevation: 4792'
Surface Cmt: 378 sx GL Elevation: 4782'
Long St Csg: 4 1/2", 11.6#, LS-75 @ 7281' TD: 7320'
Long St Cmt: 180 sx PBTD: 7200'
Long St Date: 11/1/2002

Plug Back (Sand or CIBP): CIBP
Perforation Interval (1): Niobrara Perforations: 6492' - 6566'
Perforation Interval (2): Codell Perforations: 6686' - 6695'
Perforation Interval (3): J Sand Perforations: 7144' - 7158'
Tubing: 2 3/8", 4.7#, J-55 @ 7133' Rods: _____
Pump: _____
Misc.: SN and notched collar @ EOT

PRODUCTION STATUS: Well is tripping a plunger. 3 bopd and 12 mcfd.
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH and laydown 2 3/8" tubing.
- 3) RU WL. RIH to tag CIBP or fill. PBTD @ 7200' in 2007.
- 4) RIH w/ CIBP. Set @ 7094'; dump bail 2 sx of cement on top.
- 5) RIH w/ CIBP. Set @ 6442'; dump bail 2 sx of cement on top.
- 6) Unland casing. Cut casing off @ 2500'. POOH and laydown 4 1/2" casing.
- 7) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 634'. Pump 220 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.