

WORKOVER PROCEDURE

WELL NAME:	UPV 09-05K03		DATE:	6/24/2016	
LOCATION:					
Qtr/Qtr:	SWNW	Section:	9	Township:	2N
Footages:	1646	FNL	&	990	FWL
COUNTY:	WELD		STATE:	CO	
			API #:	05-123-18218	
ENGINEER:	AJ Paine		7 Day Notice Sent:		
	(Please notify Engineer of any major changes prior to work)		Do not start operations until:		
			Notice Expires:		
OBJECTIVE:	P&A				
WELL DATA:					
Surface Csg:	8 5/8", 24# & 23#, @ 671'			KB Elevation:	4753'
Surface Cmt:	381 sx			GL Elevation:	4742'
Long St Csg:	3 1/2", 7.7#, M-70 @ 7391'			TD:	7392'
Long St Cmt:	330 sx			PBTD:	7357'
Long St Date:	6/2/1994				
Plug Back (Sand or CIBP):	Sand (Cleanout to land tubing in 1994)				
Perforation Interval (1):	J Sand Perforations: 7204' - 7264'				
Perforation Interval (2):					
Perforation Interval (3):					
Tubing:	2 1/16", 3.25#, J-55 @ 7154'			Rods:	
Pump:					
Misc.:					
PRODUCTION STATUS:	Can not support operating expense. Shut-in.				
COMMENTS:					

PROCEDURE:

- 1) Verify with AJ Paine that Form 17 has been completed and required samples have been gathered prior to RU.
 - a) Office: (720)587-2374
 - b) Cell: (406)671-4612
 - c) If Form 17 has not been completed, rig foreman to perform Form 17 and recover required samples;
 - d) Direct sample to Precision contact for analysis
- 2) MIRU Workover rig, pump & tank.
- 3) POOH and laydown 2 1/16" tubing.
- 4) RU WL. RIH w/ CIBP. Set @ 7154'.
- 5) RIH w/ workstring to pump 35 sx balance plug from 7154' - 6403' for Niobrara coverage.
- 6) Unland casing. Cut casing off @ 2500'. POOH and laydown 3 1/2" casing.
- 7) RIH w/ workstring to pump 100 sx stub plug from 2550' - 2450'. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 771'. Pump 265 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.