

## WORKOVER PROCEDURE

**WELL NAME:** Larson A25-05 **DATE:** 2/9/2016  
**LOCATION:**  
Qtr/Qtr: SWNW Section: 25 Township: 6N Range: 64W  
Footages: 1980' FNL & 660 FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16794

**ENGINEER:** NARAYAN CHOUDHARY 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 351' KB Elevation: 4628'  
Surface Cmt: 320 sx GL Elevation: 4619'  
Long St Csg: 2 7/8" 6.5# N-80 @ 6947' TD: 6969'  
Long St Cmt: 240 sx PBTD: 6942'  
Long St Date: 4/1/1993

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6807' - 6819'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 1/2" @ 6789' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: Csg Patch @ 5240'

**PRODUCTION STATUS:** SI  
**COMMENTS:** UNECONOMIC FOR WBI WORK

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6757'.
- 4) RIH w/ workstring pump 15sx of cement at 6757'.
- 5) RIH w/WL. Run CBL to confirm Casin Repair Cement.
- 6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 7) POOH to pump 100 sx stub plug @ 2500'. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 550'. Pump 170 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.