

WORKOVER PROCEDURE

WELL NAME: LOT O23-25 **DATE:** 7/6/2016
LOCATION:
Qtr/Qtr: SW/SW Section: 23 Township: 4N Range: 67W
Footages: 940 FSL & 1291 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-22308

ENGINEER: JOSH CHEBUL 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 411' KB Elevation: 4902'
Surface Cmt: 280 sx GL Elevation: 4892'
Long St Csg: 4-1/2" 11.6# M-80 @ 7430' TD: 7450'
Long St Cmt: 150 sx PBTD: 7386'
Long St Date: 2/28/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7169'-7189'
Perforation Interval (2): Codell Perforations 7269'-7289'
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 7258' Rods: N/A
Pump: _____
Misc.: _____
Misc.: _____

PRODUCTION STATUS: Producing
COMMENTS: Uneconomic to continue to produce

PROCEDURE:

- 1) Confirm bradenhead Form 17 has been performed within the last year and that a sample has been taken, if required. If a Form 17 has not been performed, rig foreman to perform Form 17 and recover any necessary samples; direct sample to DIG/Precision contact for analysis.
- 2) MIRU workover rig, pump & tank.
- 3) POOH w/ 2-3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 7119'. Dump bail 2 sx of cement on top. Top of plug: 7093'.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing and lay down on trailer.
- 6) RIH w/ tubing to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. Bottom of plug: 2500'. Top of plug: 2290'. (assumes 10" hole)
- 7) POOH w/ tubing to 526'. Pump 250 sx shoe plug (assumes 10" hole). Cement to surface. Bottom of plug: 526'. Top of plug: surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. RDMOL.