

WORKOVER PROCEDURE

WELL NAME: FOSS 14-41 **DATE:** 7/12/2016

LOCATION: Qtr/Qtr: NESE Section: 14 Township: 6N Range: 64W

Footages: 2196 FSL & 717 Township: 6N FEL 717 Range: 64W

COUNTY: WELD **STATE:** CO **API #:** 05-123-26498

ENGINEER: JASON LEHMAN 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 530' KB Elevation: 4695'
Surface Cmt: 350 sx GL Elevation: 4679'
Long St Csg: 4-1/2" 11.6# M-80 @ 6960' TD: 7021'
Long St Cmt: 1293 sx PBDT: 6935'
Long St Date: 11/1/2008

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 6567'-6584'; 6676'-6700'
Perforation Interval (2): Codell Perforations: 6855'-6866'
Perforation Interval (3): _____
Tubing: 2-3/8" @ 6846' Rods: _____
Pump: _____
Misc.: High cement top ~1204'

PRODUCTION STATUS: SI for emissions compliance
COMMENTS: P&A for offset horizontal wells

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6517', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 50 sx balance plug @ 2500'. SI, WOC. If circulation maintained no need to tag plug.
- 5) Unland casing. Cut casing off @ ~1200'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 630'. Pump 210 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.