

WORKOVER PROCEDURE

WELL NAME: FOSS 14-42 **DATE:** 12/16/2015

LOCATION: Qtr/Qtr: NWSE Section: 14 Township: 6N Range: 64W

Footages: 2186 FSL & 2167 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-24300

ENGINEER: JASON LEHMAN 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 456' KB Elevation: 4707'
Surface Cmt: 210 sx GL Elevation: 4697'
Long St Csg: 4-1/2" 11.6# M-80 @ 6977' TD: 7030'
Long St Cmt: 690 sx PBDT: 6957'
Long St Date: 12/5/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 6560'-6574'; 6660'-6680'
Perforation Interval (2): Codell Perforations: 6830'-6842'
Perforation Interval (3): _____
Tubing: 2-3/8" @ 6803' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI for emissions compliance
COMMENTS: P&A for offset horizontal wells

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6510', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 556'. Pump 184 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.

NOBLE ENERGY INC.
 FOSS 14-42
 NWSE 14-6N-64W
 2186 FSL & 2167 FEL
 WELD COUNTY, CO
 Wattenberg
CURRENT WELLBORE SCHEMATIC
 with PROPOSED P&A
 12/16/2015

API: 05-123-24300
 COGCC #

GL Elev: 4697'
 KB Elev: 4707'


Spud Date:

Surface Casing :
 8-5/8" 24# @ 456'
 Cement: 210
 TOC: Surface

TOC @ 3246'

Nio Top 6560'

Production Casing :
 4-1/2" 11.6# M-80 @ 6977'
 Cement: 690
 TD: 12/5/2006



Cut surface casing off 6'-8' below surface.

Pump approx 184 sx shoe plug @ 556'
Will bring cement to surface.

Pump 125 sx stub plug where csg was pulled
Cut and pull csg @ 2500'

CIBP @ 6510' w/ 2 sx cement on top

Niobrara Perforations:
6560'-6574'; 6660'-6680'

Codell Perforations: 6830'-6842'

TD: 7030'