

**WORKOVER PROCEDURE**

**WELL NAME:** FOSS 14-43 **DATE:** 7/13/2016

**LOCATION:**  
Qtr/Qtr: SWSE Section: 14 Township: 6N Range: 64W  
Footages: 498 FSL & 2162 FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-26500

**ENGINEER:** JASON LEHMAN 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8-5/8" 24# @ 461' KB Elevation: 4687'  
Surface Cmt: 250 sx GL Elevation: 4675'  
Long St Csg: 4-1/2" 11.6# M-80 @ 7023' TD: 7050'  
Long St Cmt: 1230 sx PBSD: 7022'  
Long St Date: 11/27/2007

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations: 6550'-6566'; 6668'-6684'  
Perforation Interval (2): Codell Perforations: 6834'-6847'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2-3/8" 4.7# J-55 @ 6816' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) Confirm that a Form 42 was filed, Form 17 has been performed and sample taken (only if required). If a Form 17 has not been performed, rig foreman to perform Form 17 and necessary sampling if required.
- 2) MIRU Workover rig, pump & tank.
- 3) POOH w/ 2-3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6500', dump bail 2 sx of cement on top.
- 5) RIH w/ workstring to pump 50 sx balance plug @ 2500'. SI, WOC. If circulation maintained no need to tag plug.
- 6) RIH w/ workstring to 561'. Pump 43 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Add cement to the backside until at surface.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.