

WORKOVER PROCEDURE

WELL NAME: DCD FARM A26-02 **DATE:** 2/16/2016
LOCATION:
Qtr/Qtr: NW/NE Section: 26 Township: 6N Range: 64W
Footages: 760' FNL & 1990' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-26387

ENGINEER: NARAYAN CHOUDHARY 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 829' KB Elevation: 4645'
Surface Cmt: 403 sx GL Elevation: 4633'
Long St Csg: 4 1/2" 11.6# M-80 @ 6967' TD: 6998'
Long St Cmt: 910 sx PBTD: 6932'
Long St Date: 1/24/2008

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 6805' to 6818'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 3/8" 4.7# J-55 @ 6790' Rods:
Pump:
Misc.:

PRODUCTION STATUS: SI
COMMENTS: Uneconomic for WBI work

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6755'. RIH w/ workstring to pump 30 sx on top of CIBP. POOH w/ workstring.
- 4) Unland casing. Cut casing off @ 1640'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 950'. Pump 300 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.