

WORKOVER PROCEDURE

WELL NAME: Lower Latham 2-12G **DATE:** 8/9/2016

LOCATION: Qtr/Qtr: NWSE Section: 2 Township: 4N Range: 65W

Footages: 1929 FSL & 2095 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-17176

ENGINEER: Garrett Reddin 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 23# @ 465' KB KB Elevation: 4682'
Surface Cmt: 280 sx GL Elevation: 4671'
Long St Csg: 4-1/2" 11.6# M-75 @ 8045' KB TD: 8055' KB
Long St Cmt: 550 sx PBTD: 8006' KB
Long St Date: 8/10/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 7590-7730' KB
Perforation Interval (2): Codell Perforations: 7908-7920' KB
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 7889' KB Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: PR
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7540', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring. Pump 30 sx balance plug at 4420'.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 565'. Pump 195 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.