



photo 1: Facing southwest along the main access road. There are signs of erosion occurring along the road.



photo 2: Facing southwest along the main access road. Stormwater is being down the road causing erosion on the road. The cut slope is not stabilized and there are signs of erosion occurring.



photo 3: Erosion occurring along the road has created a 3 ½ foot hole as indicated by the shovel which red arrow points to.



photo 4: Stormwater is flowing across the access road at this point causing erosion across and along the fill slope of the access road.



photo 5: Facing west toward the cut slope at the location..



photo 6: Stormwater run-on is causing erosion along the cut slope.



photo 7: Sediment is being deposited off the cut slope into the berm area of this tank.



photo 8: South side of the location facing west.



photo 9: Facing north along the fill slope at the east side of location.



photo 10: Facing east off the fill slope. There is erosion occurring down off the slope.