

WORKOVER PROCEDURE

WELL NAME: Stromberger 39-12 **DATE:** 8/31/2016

LOCATION:
Qtr/Qtr: SESE Section: 12 Township: 4N Range: 66W
Footages: 566 FSL & 548 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-26473

ENGINEER: Jeanne Van Slambrouck **7 Day Notice Sent:** _____
(Please notify Engineer of any major changes prior to work) **Do not start operations until:** _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8", J-55, 24# @ 547' KB Elevation: 4,717
Surface Cmt: 270 sx GL Elevation: 4,705
Long St Csg: 4-1/2", I-80, 11.60# @ 7,439' TD: 7,450
Long St Cmt: 535 sx PBTD: 7,379
Long St Date: 11/2/2007

Plug Back (Sand or CIBP): **Sand**
Perforation Interval (1): Niobrara Perforations: 6,963' - 7,155'
Perforation Interval (2): Codell Perforations: 7,266' - 7,281'
Perforation Interval (3): _____
Tubing: 2-3/8", J-55, 4.70# @ 7,238' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing, 1 bopd and 35 mcfd, 360# / 375#
COMMENTS: Uneconomic to do annular fill and STEM

PROCEDURE:

- 1) Ensure Form 17 has been performed.
- 2) MIRU Workover rig, pump & tank.
- 3) POOH w/ 2-3/8" tbg and lay down.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 6,913', dump bail 2 sx of cement on top.
- 5) RIH w/ workstring. Pump 25 sx balance plug across the Sussex from 3,954' to 4,254'.
- 6) Unland casing. Cut casing off @ 2,500'. POOH w/ casing laying down on trailer.
- 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. Plug should extend from at least 2450' to 2550'. If maintain circulation, no need to tag plug.
- 8) POOH to 650'. Pump 230 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.