

**WORKOVER PROCEDURE**

**WELL NAME:** Schmidt 2-26 **DATE:** 8/31/2016

**LOCATION:** Qtr/Qtr: NW/NE Section: 26 Township: 4N Range: 66W

Footages: 663 FNL & 1990 FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-17913

**ENGINEER:** Jeanne Van Slambrouck 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 560' KB Elevation: 4752'  
Surface Cmt: 390 sx GL Elevation: 4742'  
Long St Csg: 4 1/2" 11.6#, I-70 @ 7390' TD: 7395'  
Long St Cmt: 425 sx PBTD: 7340'  
Long St Date: 1/30/1994

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6938' - 7119'  
Perforation Interval (2): Codell Perforations 7235' - 7248'  
Perforation Interval (3): \_\_\_\_\_  
Perforation Interval (4): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 tbg @ 7203' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** Provide 48 hr notice of plugging MIRU via electronic form 42.  
Abandon flowlines as per Rule 1103. File electronic form 42 once abandonment completed.

- PROCEDURE:**
- 1) Prior to plugging operations, perform a bradenhead test.
  - 2) MIRU Workover rig, pump & tank.
  - 3) POOH w/ 2 3/8" tbg and lay down.
  - 4) RIH w/ workstring w/ tubing-set CIBP. Set CIBP @ 6888', dump bail 2 sx of cement on top.
  - 5) POOH w/ workstring to 4300' and pump 20 sx balance plug across sussex.
  - 6) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
  - 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
  - 8) POOH w/ workstring to 710'. Pump 275 sx shoe plug. Cement to surface.
  - 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
  - 10) Cut surface casing off 6'-8' below ground.
  - 11) Clean up location. Reclaim location. RDMO.