

WORKOVER PROCEDURE

WELL NAME: ALM USX E13-11 **DATE:** 8/31/2016

LOCATION:
Qtr/Qtr: NW/SW Section: 11 Township: 6N Range: 65W
Footages: 1828 FSL & 508 FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-23305

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24.0#, Grade ? @ 476' KB Elevation: 4788'
Surface Cmt: 340 sx GL Elevation: 4775'
Long St Csg: 4 1/2" 11.60#, N-80 @ 7295' TD: 7321'
Long St Cmt: 410 sx PBTD: 7247'
Long St Date: 12/22/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7160' - 7174'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70#, J-55 @ 7147' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7110', pump 26 sx of cement on top.
- 4) RIH w/ workstring to pump 50 sx csg plug @ 2500'
- 5) POOH w/ workstring to 576'. Pump 44 sx shoe plug. Cement to surface.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. RDMOL.